



SAFETY DATA SHEET (SDS)

		SAFETT DATA Section 1. Ident					
Product identifier	Metaflux 70-18		meation				
Other means of identificati		enioniai spray					
Recommended use and restrictions on COATING/AEROSOL							
use	reștrictionș on	COMING/ALROSOL					
Initial supplier identifier	AMETA SOL	UTION.COM 1392. AVENUE	DE LA GARE, MASCOUCHE, (QU	ÉBEC). J7K 2Z2. CANADA			
		7-3102 & (888) 452-6382 WW		,,,,,			
Emergency telephone num			24 hour number 613-996-6666				
	Section 2. Hazard identification						
Classification of hazardous product (name of the category or subcategory of the hazard class)							
Extremely flammable aerosol (Category 1)							
Gas under pressure (compressed gas)							
Skin irritation (Category 2)							
Eye irritation (Category 2A)							
Aspiration hazard (Category 1)							
Specific target organ toxicity – single exposure (Category 3), Central nervous system							
	Reproductive toxicity (Category 2)						
Information elements (symbols, signal words, hazard statements and precautionary statements of the category/subcategory)							
 Thromation retained symbols, signal words, hazard statements and precadmonary statements of the Category/subcategory) Danger H222 Extremely flammable aerosol. H229 Pressurized container: may burst if heated. H280 Contains gas under pressure; may explode if heated. H304 May be fatal if swallowed and enters airways. H315 Causes skin irritation. H319 Causes serious eye irritation. H361 Suspected of damaging fertility or the unborn child. *** May displace oxygen and cause rapid suffocation. P201 Obtain special instructions before use. P202 Do not handle until all safety precautions have been read and understood. P210 Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. P211 Do not spray on an open flame or other ignition source. P251 Do not pierce or burn, even after use. P261 Avoid breathing dust/fume/gas/mist/vapours/spray. P264 Wash hands/nails/face thoroughly after handling. P271 Use only outdoors or in a well-ventilated area. P280 Wear gloves/protective clothing/eye protection/face protection. P301 + P310 IF SWALLOWED: Immediately call a doctor. P331 DO NOT INDUCE VOMITING. P302 + P352 IF ON SKIN: wash with plenty of water. P333 + P313 IF SKIN irritation or rash occurs: Get medical attention. P304 + P340 IF INHALED: Remove person to fresh air and keep comfortable for breathing. P312 Call a doctor if you feel unwell. P308 + P313 IF exposed or concerned: Get medical attention. P410+P412+P403+P233 Protect from sunlight. Do not expose to temperatures exceeding on °C/122 °F. Store in a well-ventilated area. Keep container tightly closed. P405 Store locked up. P501 Dispose of contents/container tightly closed. P405 Store locked up. P501 Dispose of contents/container tightly closed. P405 Store locked up. P501 Dispose of contents/container tightly closed. P405 Store locked up. P501 Dispose of contents/container into safe 							
container in accordance with	Circula A subarr	initional regulations.	·				
Other hazards known		iants (Category 1) A gas that					
		ction 3. Composition/infor	0				
Chemical name (common 1	name/synonyms)		CAS number or other	Concentration (%)*			
Butane			106-97-8	25-50			
Acetone			67-64-1 74-98-6	20-25			
Propane				10-25			
Xylenes			1330-20-7	10-12.5			
Toluene			108-88-3	< 5			
Ethyl benzene		100-41-4	< 3 < 3				
* Statement - This safety data sh	neet provides concer	All ingredients are listed according tration range(s) instead of the actual	ng to OSHA (29 CFR). l concentration(s) considered trade secret	(s).			



	Section 4. First-aid measures					
Inhalation	IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a doctor if you feel unwell.					
Ingestion	IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a doctor if you feel unwell. IF SWALLOWED: Immediately call a doctor. DO NOT INDUCE VOMITING. NEVER give anything by mouth if victim is					
ingestion	rapidly losing consciousness, or is unconscious or convulsing. Rinse mouth thoroughly with water. Have victim drink t					
	glasses of water. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration.					
Skin contact	IF ON SKIN: wash with plenty of water. (15-20 minutes) IF SKIN irritation or rash occurs: Get medical attention. Take off					
Skin contact	contaminated clothing and wash it before reuse.					
Eye contact	IF IN EYES, Rinse cautiously with water for several minutes (15-20). Remove contact lenses, if present and easy to do.					
Lye contact	Continue rinsing. If eye irritation persists: Get medical attention.					
Most important	symptoms and effects (acute or delayed) Causes skin irritation. Causes serious eye irritation.					
	mediate medical attention/special treatment In all cases, call a doctor. Do not forget this document.					
Indication of im	Section 5. Fire-fighting measures					
Specific hazarde	s of the hazardous product (hazardous combustion products)					
•	d other irritant/toxic gases and fumes.					
Suitable and unsuitable extinguishing media						
	se carbon dioxide, chemical powder agent and appropriate foam to extinguish.					
	ve equipment and precautions for fire-fighters					
	tating/toxic smoke and fumes may be generated. Do not enter fire area without proper protection. Firefighters should wear proper					
	nent and self-contained breathing apparatus with full facepiece. Shield personnel to protect from venting, rupturing or bursting cans.					
Move containers	from fire area if it can be done without risk. Water spray may be useful in cooling equipment and cans exposed to heat and flame.					
	Section 6. Accidental release measures					
Personal precau	tions, protective equipment and emergency procedures					
	o area until completion of clean-up. Ensure clean-up is conducted by trained personnel only. All persons dealing with clean-up					
should wear the a	ppropriate protective equipment (See Section 8).					
	aterials for containment and cleaning up					
Avoid release to	the environment. Collect spillage. Ventilate area of release. Stop the leak if it can be done safely. Contain and absorb any spilled					
liquid concentrate with inert absorbent material, then place material into a container for later disposal (see Section 13). Contaminated absorbent						
material may pose	e the same hazards as the spilled product. Notify the appropriate authorities as required.					
	Section 7. Handling and storage					
Precautions for						
	light. Do not expose to temperatures exceeding 50 °C/122 °F. Keep away from heat/sparks/open flames/hot surfaces No					
smoking. Do not spray on an open flame or other ignition source. Do not pierce or burn, even after use. Use only outdoors or in a well-ventilated						
	spray on an open flame or other ignition source. Do not pierce or burn, even after use. Use only outdoors or in a well-ventilated					
area. Wash hands	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection.					
area. Wash hands Before handling,	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene					
area. Wash hands Before handling, measures are be	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect					
area. Wash hands Before handling, measures are be containers for	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high					
area. Wash hands Before handling, measures are be containers for dust/fume/gas/mi concentrations of	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty					
area. Wash hands Before handling, measures are be containers for dust/fume/gas/mi concentrations of containers are alw	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-vo	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10).					
area. Wash hands Before handling, measures are be containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). hing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of					
area. Wash hands Before handling, measures are be containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-we Inspect all incom obstruction and a	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). hing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values)					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits:	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). hing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm &	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-tWA 100 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T	Synails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV- TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 'WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm);					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng	Synails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). high containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-twa 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 'WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm);					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well-	Schails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-tot TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); gincering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. N	Schails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-t TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); pincering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. I Individual prote	Whails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing st/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). hing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-& TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-& TUV-STEL 750 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below. Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. I Individual prote	Schails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-t TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); pincering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-vi Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. I Individual prote Respiratory prote	Whails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing st/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). hing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-& TUV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-& TUV-STEL 750 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.					
area. Wash hands Before handling, measures are bei containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-vi Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. I Individual prote Respiratory prote limits are unknow	Whails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid bereathing st/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV- TLV-STEL 750 ppm; CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); jincering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ction is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure					
area. Wash hands Before handling, measures are be containers for dust/fume/gas/mi concentrations of containers are alw Conditions for s Store in a well-vu Inspect all incom obstruction and a Control parame Exposure limits: TWA 500 ppm & ACGIH – TLV-T Appropriate eng Use under well- exposure limits. I Individual prote Respiratory prote limits are unknow be worn during a	Whails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty vays dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 74-98-6 & 75-28-5 & 106-97-8 – ACGIH – TLV-TWA (STEL) & PEL-TWA 1000 ppm; CAS 67-64-1 – ACGIH – TLV-twa 120 ppm & PEL-TWA 100 ppm; CAS 1300-20-7 ACGIH – TLV-TWA (100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 100-41-4 WA 20 ppm & PEL-TWA 100 ppm; CAS 108-88-3 – ACGIH – TLV-TWA 20 ppm & PEL-TWA 200 ppm (ceiling 300 ppm); jneering controls. Ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. etion measures/personal protective equipment ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of conta					



Section 9. Physical and c	hemical	nronertie	s					
Appearance, physical state/colour Silver liquid (aerosol)			Not available					
Odour Characteristic	Vapour pressure Vapour density		Heavier than air					
Odour threshold Not available			0.688 g/cm ³ @ 20°C					
pH Not available		Relative density 0.688 g/cm ³ @ 20°C Solubility Not miscible						
Melting/freezing point Not available	Solubility Not infection Partition coefficient - n-octanol/water Not available							
Initial boiling point/range Not available								
Flash point Not available	Auto-ignition temperatureNot availableDecomposition temperatureNot available							
Evaporation rate Not available	Viscosity Not available							
Evaporation rate Not available Flammability (solids and gases) Extremely flammable aerosol	VISCOSIC	Not availa						
Upper and lower flammability/explosive limits Not available	Other	None kno						
Section 10. Stability			WII					
Reactivity								
Does not react under the recommended storage and handling conditions preserved								
Chemical stability								
Stable under the recommended storage and handling conditions prescribed.								
Possibility of hazardous reactions								
Accumulation of flammable if product is heated. Do not spray on an open	flame or o	ther ignitic	on source. Do not pierce or burn, even after use.					
Protect from sunlight. Do not expose to temperatures exceeding 50 °C/122 °I								
Conditions to avoid (static discharge, shock or vibration)								
	Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Do not spray on an open flame or other ignition							
source. Do not pierce or burn, even after use. Protect from sunlight. Do not e								
Incompatible materials								
Oxidizing materials; etc.								
Hazardous decomposition products								
None known								
Section 11. Toxicolog	ical infor	mation						
Information on the likely routes of exposure (inhalation, ingestion, skin a								
May be fatal if swallowed and enters airways. Causes skin irritation. Causes			May agues drowsinger or dizzinger Suspected					
			i. May cause drowsiness of dizziness. Suspected					
	of damaging fertility or the unborn child. May displace oxygen and cause rapid suffocation.							
Symptoms related to the physical, chemical and toxicological characteristics Skin irritation, redness, stinging, pain; Eye irritation, redness, tearing; Respiratory tract irritation, coughing, shortness of breath, dizziness,								
drowsiness, nausea and headaches.	respiratory	tract fritta	ation, cougning, shortness of breath, dizziness,					
Delayed and immediate effects (chronic effects from short-term and long	~ town or							
Skin Sensitization – No data available;	g-term ex	posure)						
Respiratory Sensitization – No data available;								
Germ Cell Mutagenicity – No data available;								
Carcinogenicity – No ingredient listed by IARC, ACGIH, NTP or OSHA;								
Reproductive Toxicity – Possible; Specific Tarret Organ Toxicity – Single Exposure – Possible;								
Specific Target Organ Toxicity — Single Exposure – Possible; Specific Target Organ Toxicity — Repeated Exposure – No data available;								
Aspiration Hazard – Possible;								
Health Hazards Not Otherwise Classified – No data available.								
Numerical measures of toxicity (ATE; LD ₅₀ & LC ₅₀)								
CAS 75-28-5 & 106-97-8 LC_{50} 658000 mg/m ³ 4 hrs (rat); CAS 67-64-1 LD_{50} Oral - Rat - 5800 mg/kg; LC_{50} Inhalation - Rat - 8 h - 50100 mg/m ³ ;								
LD_{50} Dermal - Guinea pig - 7426 mg/kg; CAS 1330-20-7 Oral, rat LD_{50} 4300 mg/kg; Dermal, rabbit LD_{50} 12100 mg/kg; CAS 100-41-4 Oral, rat								
LD_{50} Definal - Outlie a pig - 7-20 mg/kg; CAS 1550-20-7 Oral, fat LD_{50} 4500 mg/kg; Definal, fabout LD_{50} 12100 mg/kg; CAS 100-41-4 Oral, fat LD_{50} 3500 mg/kg; Dermal, rabbit LD_{50} 15380 mg/kg; CAS 108-88-3 LD_{50} Oral - Rat - 5580 mg/kg; LC_{50} Inhalation - Rat - 4 h – 8000 ppm; LD_{50}								
Dermal - Rabbit $- 12125 \text{ mg/kg}$;								
ATE not available in this document.								
Section 12. Ecological information Ecotoxicity (aquatic and terrestrial information) No data available for this product.								
	ans produ	сı.						
Persistence and degradability No data available for this product. Bisesemulation activities No data available for this product.								
Bioaccumulative potential No data available for this product.								
Mobility in soil No data available for this product. Other adverse effects No data available for this product.								
	Section 13. Disposal considerations							
Information on safe handling for disposal/methods of disposal/contamin			1.1					
Dispose of contents/container into safe container in accordance with local, re	egional or i	national reg	gulations.					



Section 14. Transport information					
	Proper shipping name; Class(es); Packing group (PG) of the TDG Regulations				
	OSOLS; CLASS 2.1				
UN number; Proper shipping name; Class(es); Packing group (PG) of the 49 CFR (USA)					
	OSOLS; CLASS 2.1				
	Proper shipping name; Class(es); Packing group (PG) of the IMDG (maritime)				
UN1950; AER	OSOLS; CLASS 2.1;				
	Proper shipping name; Class(es); Packing group (PG) of the IATA (air)				
UN1950; AER	OSOLS, FLAMMABLE; CLASS 2.1				
Special precautions (transport/conveyance) May also be shipped as a LIMITED QUANTITY in accordance with TDG.					
Environmental hazards (IMDG or other) None known					
Bulk transport (usually more than 450 L in capacity) Not possible					
•	Section 15. Regulatory information				
Safety/health Canadian regulations specifics Refer to Section 2 for the appropriate classification. This product has been					
Saroty, Incarrie	accordance with the hazard criteria of the Hazardous Products Regulations (HPR) and of the				
	United States OSHA (29 CFR).				
Environmenta	al Canadian regulations specifics Refer to Section 3 for ingredient(s) of the DSL				
	environmental outside regulations specifics				
	DSHA information: This product is regulated according to OSHA (29 CFR).				
	EPA (Environmental Protection Agency) information: 40 CFR Refer to the ingredients listed in Section 3 & Sections 12; 13 & 14.				
	ICSA information: Refer to the ingredients listed in Section 3.				
	Protection Association (NFPA):				
HEALTH: 1					
	ALE: $0 = \text{Minimal} 1 = \text{Slight} 2 = \text{Moderate} 3 = \text{Serious} 4 = \text{Severe}$				
	position 65: WARNING This product contains Toluene (CAS 108-88-3) & Ethyl benzene (CAS 100-41-4) known to the State of				
	use cancer or other reproductive harm.				
	Section 16. Other information				
Date of the lat	test revision of the safety data sheet DATE: 2025-02-05				
References	Safety Data Sheets from manufacturer/supplier & from Canadian Centre for Occupational Health and Safety, CCOHS.				
Abbreviations					
ACGIH	American Conference of Governmental Industrial Hygienists				
ATE	Acute toxicity estimate				
CAS	Chemical Abstract Service				
DSL	Domestic Substance List				
IARC	International Agency for Research on Cancer				
IATA	International Agency for Research on Cancer International Air Transport Association				
IMDG	International Maritime Dangerous Goods Code				
LC	Lethal concentration				
LD	Lethal Dosage				
NIOSH	National Institute for Occupational Safety and Health				
NTP	National Toxicology Program (U.S.A.)				
OSHA	Occupational Safety and Health Administration (U.S.A.)				
PEL	Permissible Exposure Limit				
STEL	Short-term Exposure Limit				
TDG	Transport of dangerous goods in Canada				
TLV	Threshold Limit Value				
TSCA	Toxic Substances Control Act				
TWA					
	Time Weighted Average Workplace Hazardous Materials Information System				
	WHMIS Workplace Hazardous Materials Information System To the best of our knowledge, the information contained herein is accurate. However, neither the above named supplier nor any of its subsidiaries assumes any				
	liability whatsoever for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility				
	materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that				
	these are the only hazards that exist				

these are the only hazards that exist.