

use

Danger



SAFETY DATA SHEET (SDS) Section 1. Identification **Product identifier** Metaflux 70-46 Zink Grund Spray **Other means of identification** 70-46 Recommended use and restrictions on COATING/AEROSOL AMETA SOLUTION.COM 1392, AVENUE DE LA GARE, MASCOUCHE, (QUÉBEC), J7K 2Z2, CANADA Initial supplier identifier TÉL. (450) 477-3102 & (888) 452-6382 WWW.AMETASOLUTION.COM **Emergency telephone number/restriction on use** Canada – CANUTEC 24 hour number 613-996-6666 Section 2. Hazard identification Classification of hazardous product (name of the category or subcategory of the hazard class) Extremely flammable aerosol (Category 1) Gas under pressure (compressed gas) Skin irritation (Category 2) Eye irritation (Category 2A) Aspiration hazard (Category 1) Specific target organ toxicity - single exposure (Category 3), Central nervous system Hazardous to the aquatic environment – Acute & Chronic (Category 1) Information elements (symbols, signal words, hazard statements and precautionary statements of the category/subcategory)

H222 Extremely flammable aerosol.

H229 Pressurized container: may burst if heated.

H280 Contains gas under pressure; may explode if heated.

H304 May be fatal if swallowed and enters airways.

H315 Causes skin irritation.

H319 Causes serious eye irritation.

H336 May cause drowsiness or dizziness.

H410 Very toxic to aquatic life with long lasting effects.

*** May displace oxygen and cause rapid suffocation. P210 Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. P211 Do not spray on an open flame or other ignition source. P251 Do not pierce or burn, even after use. P261 Avoid breathing dust/fume/gas/mist/vapours/spray. P264 Wash hands/nails/face thoroughly after handling. P271 Use only outdoors or in a well-ventilated area. P273 Avoid release to the environment. P280 Wear gloves/protective clothing/eye protection/face protection. P301 + P310 IF SWALLOWED: Immediately call a doctor. P331 DO NOT INDUCE VOMITING. P302 + P352 IF ON SKIN: wash with plenty of water. P333 + P313 IF SKIN irritation or rash occurs: Get medical attention. P362 + P364 Take off contaminated clothing and wash it before reuse. P305 + P351 + P338 IF IN EYES, Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P337 + P313 If eye irritation persists: Get medical attention. P304 + P340 IF INHALED: Remove person to fresh air and keep comfortable for breathing. P312 Call a doctor if you feel unwell. P391 Collect spillage. P410+P412+P403+P233 Protect from sunlight. Do not expose to temperatures exceeding 50 °C/122 °F. Store in a well-ventilated area. Keep container tightly closed. P405 Store locked up. P501 Dispose of contents/container into safe container in accordance with local, regional or national regulations.

Other hazards known	Simple Asphyxiants (Category 1) A gas that is a simple asphyxiant***					
Section 3. Composition/information on ingredients						
Chemical name (common name/synonyms)		CAS number or other	Concentration (%)*			
Dimethyl ether		115-10-6	30-60			
Zinc, powder		7440-66-6	2.5-25			
Acetone		67-64-1	1-10			
Xylenes		1330-20-7	1-13			
Naphtha (petroleum), desulfurized heavy		64742-82-1	2.5-25			
Zinc oxide		1314-13-2	< 3			
n-Butanol		71-36-3	1-5			
		ted according to OSHA (29 CFR).	·			

* Statement - This safety data sheet provides concentration range(s) instead of the actual concentration(s) considered trade secret(s).



T I I <i>I</i>	Section 4. First-aid measures			
Inhalation	IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a doctor if you feel unwell.			
Ingestion	IF SWALLOWED: Immediately call a doctor. DO NOT INDUCE VOMITING. NEVER give anything by mouth if victin			
	rapidly losing consciousness, or is unconscious or convulsing. Rinse mouth thoroughly with water. Have victim drink two			
	glasses of water. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration.			
Skin contact	IF ON SKIN: wash with plenty of water. (15-20 minutes) IF SKIN irritation or rash occurs: Get medical attention. Take of			
	contaminated clothing and wash it before reuse.			
Eye contact	IF IN EYES, Rinse cautiously with water for several minutes (15-20). Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention.			
Most important	symptoms and effects (acute or delayed) Causes skin irritation. Causes serious eye irritation.			
	mediate medical attention/special treatment In all cases, call a doctor. Do not forget this document.			
	Section 5. Fire-fighting measures			
Specific hazards	s of the hazardous product (hazardous combustion products)			
	nd other irritant/toxic gases and fumes.			
	suitable extinguishing media			
	se carbon dioxide, chemical powder agent and appropriate foam to extinguish.			
	ve equipment and precautions for fire-fighters			
	itating/toxic smoke and fumes may be generated. Do not enter fire area without proper protection. Firefighters should wear proper			
	nent and self-contained breathing apparatus with full facepiece. Shield personnel to protect from venting, rupturing or bursting cans.			
	from fire area if it can be done without risk. Water spray may be useful in cooling equipment and cans exposed to heat and flame.			
	Section 6. Accidental release measures			
Personal precau	tions, protective equipment and emergency procedures			
	o area until completion of clean-up. Ensure clean-up is conducted by trained personnel only. All persons dealing with clean-up			
	ppropriate protective equipment (See Section 8).			
	aterials for containment and cleaning up			
	the environment. Collect spillage. Ventilate area of release. Stop the leak if it can be done safely. Contain and absorb any spilled			
	e with inert absorbent material, then place material into a container for later disposal (see Section 13). Contaminated absorbent			
	e the same hazards as the spilled product. Notify the appropriate authorities as required.			
21	Section 7. Handling and storage			
Precautions for				
	light. Do not expose to temperatures exceeding 50 °C/122 °F. Keep away from heat/sparks/open flames/hot surfaces No			
area. Wash hand	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection.			
area. Wash hand Before handling,	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene			
area. Wash hand Before handling, measures are be	it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect			
area. Wash hand Before handling, measures are be containers for	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are all	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygienering followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10).			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8.			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are ab Conditions for s Store in a well-v Inspect all incor	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygienering followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10).			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are ab Conditions for s Store in a well-v Inspect all incor	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks.			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alw Conditions for s Store in a well-v Inspect all incor obstruction and a	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alw Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values)			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are all Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits:	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alw Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygieneing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA 20 ppm;			
area. Wash hand: Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alw Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA 2 mg/m ³ (STEL 10 mg/m ³); CAS 71-36-3 ACGIH – TLV-TWA 20 ppm; gineering controls			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well-	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA -STEL 750 ppm; CAS 1314-13-2 ACGIH – TLV-TWA 2 mg/m ³ (STEL 10 mg/m ³); CAS 71-36-3 ACGIH – TLV-TWA 20 ppm; gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well- exposure limits.	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of iccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA -STEL 750 ppm; CAS 1314-13-2 ACGIH – TLV-TWA 2 mg/m ³ (STEL 10 mg/m ³); CAS 71-36-3 ACGIH – TLV-TWA 20 ppm; gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well- exposure limits.	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high 'dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ining containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA 2 mg/m ³ (STEL 10 mg/m ³); CAS 71-36-3 ACGIH – TLV-TWA 20 ppm; gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well- exposure limits. Individual prote Respiratory prot	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA 20 ppm; 2incering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ection measures/personal protective equipment ection is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well- exposure limits. Individual prot Respiratory prot limits are unknow	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA -STEL 750 ppm; CAS 1314-13-2 ACGIH – TLV-TWA 2 mg/m ³ (STEL 10 mg/m ³); CAS 71-36-3 ACGIH – TLV-TWA 20 ppm; gineering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. section measures/personal protective equipment ection is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure wn. Chemically protective gloves (impervious), and other protective clothing to prevent prolonged or repeated skin contact, must			
area. Wash hand Before handling, measures are be containers for dust/fume/gas/m concentrations of containers are alv Conditions for s Store in a well-v Inspect all incor obstruction and a Control parame Exposure limits: 500 ppm & TLV Appropriate en Use under well- exposure limits. Individual prote Respiratory prot limits are unknow be worn during a	s/nails/face thoroughly after handling. Wear gloves/protective clothing/eye protection/face protection. it is very important that engineering controls are operating, and that protective equipment requirements and personal hygiene ing followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect leaks before handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing ist/vapours/spray. Avoid contact with eyes, skin and clothing. Keep away from heat, sparks and flame. Avoid generating high dusts, vapours or mists. Keep away from incompatible materials (Section 10). Keep containers closed when not in use. Empty ways dangerous. Refer also to Section 8. afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10). ning containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of accessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 1330-20-7 ACGIH – TLV-TWA 100 ppm (STEL 150 ppm) & PEL-TWA 100 ppm; CAS 67-64-1 – ACGIH – TLV-TWA 20 ppm; 2incering controls ventilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below Make emergency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ection measures/personal protective equipment ection is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure			



Section 9. Physical and c	hemical p	oroperties	3		
Appearance, physical state/colour Liquid (aerosol)	Vapour	pressure	Not available		
Odour Characteristic		density	Heavier than air		
Odour threshold Not available			Not available		
pH Not available			zailable		
Melting/freezing point Not available Partition coefficient - n-octanol/water Not available					
Initial boiling point/range Not available	Auto-ignition temperature Not available				
Flash point Not available		osition tem			
Evaporation rate Not available	Viscosity				
Flammability (solids and gases) Extremely flammable aerosol		Not availa			
Upper and lower flammability/explosive limits Not available	VOC Other				
Section 10. Stability and reactivity					
Reactivity		v			
Does not react under the recommended storage and handling conditions prescri	bed.				
Chemical stability					
Stable under the recommended storage and handling conditions prescribed.					
Possibility of hazardous reactions					
Accumulation of flammable if product is heated. Do not spray on an open f	flame or of	ther ignition	n source. Do not pierce or hurn even after use		
Protect from sunlight. Do not expose to temperatures exceeding 50 °C/122 °F		uner ignitio	in source. Do not pierce of burn, even after use.		
Conditions to avoid (static discharge, shock or vibration)	•				
Keep away from heat, hot surfaces, sparks, open flames and other ignition so	ources No	smoking	Do not spray on an open flame or other ignition		
source. Do not pierce or burn, even after use. Protect from sunlight. Do not ex					
Incompatible materials	Apose to te	mperatures			
Oxidizing materials; etc.					
Hazardous decomposition products					
None known					
Section 11. Toxicologi					
Information on the likely routes of exposure (inhalation, ingestion, skin a					
May be fatal if swallowed and enters airways. Causes skin irritation. Causes serious eye irritation. May cause drowsiness or dizziness. May					
displace oxygen and cause rapid suffocation.					
Symptoms related to the physical, chemical and toxicological characteris		, ,,			
Skin irritation, redness, stinging, pain; Eye irritation, redness, tearing; R- drowsiness, nausea and headaches.	espiratory	tract irrita	tion, coughing, shortness of breath, dizziness,		
Delayed and immediate effects (chronic effects from short-term and long	torm orn	osuro)			
Skin Sensitization – No data available;	g-term exp	usure)			
Respiratory Sensitization – No data available;					
Germ Cell Mutagenicity – No data available;					
Carcinogenicity – No ingredient listed by IARC, ACGIH, NTP or OSHA;					
Reproductive Toxicity – No data available; Specific Target Organ Toxicity — Single Exposure – Possible;					
Specific Target Organ Toxicity — Repeated Exposure – No data available;					
Aspiration Hazard – Possible;					
Health Hazards Not Otherwise Classified – No data available.					
Numerical measures of toxicity (ATE; LD ₅₀ & LC ₅₀)					
	4300 mg/	ka I D. D	ermal_rabbit 12100 mg/kg: CAS 67_64_1 LD		
CAS 115-10-6 LC ₅₀ 164000 ppm 4 hrs (rat); CAS 1330-20-7 LD ₅₀ Oral, rat 4300 mg/kg; LD ₅₀ Dermal, rabbit 12100 mg/kg; CAS 67-64-1 LD ₅₀ Oral - Rat - 5800 mg/kg; LC ₅₀ Inhalation - Rat - 8 h - 50100 mg/m ³ ; LD ₅₀ Dermal - Guinea pig - 7426 mg/kg; CAS 1314-13-2 LD ₅₀ Oral - Rat -					
$7950 \text{ mg/kg}; \text{CAS } 71-36-3 \text{ LD}_{50} \text{ Oral - Rat - } 790 \text{ mg/kg};$					
ATE not available in this document.					
	al inform	ation			
Section 12. Ecological information Ecotoxicity (aquatic and terrestrial information) No data available for this product.					
Persistence and degradability No data available for this product. Biogeonumulative potential No data quailable for this product.					
Bioaccumulative potential No data available for this product. Mobility in soil No data available for this product.					
Mobility in soil No data available for this product. Other adverse effects Very toxic to aquatic life with long lasting effects.					
Section 13. Disposal considerations					
Information on safe handling for disposal/methods of disposal/contamina			1.1		
Dispose of contents/container into safe container in accordance with local, regional or national regulations.					



Section 14. Transport information					
	oper shipping name; Class(es); Packing group (PG) of the TDG Regulations				
UN1950; AERO	SOLS; CLASS 2.1				
UN number; Pr	oper shipping name; Class(es); Packing group (PG) of the 49 CFR (USA)				
UN1950; AERO	SOLS; CLASS 2.1				
UN number; Pr	oper shipping name; Class(es); Packing group (PG) of the IMDG (maritime)				
	SOLS; CLASS 2.1; MARINE POLLUTANT				
	oper shipping name; Class(es); Packing group (PG) of the IATA (air)				
	SOLS, FLAMMABLE; CLASS 2.1				
	ions (transport/conveyance) May also be shipped as a LIMITED QUANTITY in accordance with TDG.				
	hazards (IMDG or other) MARINE POLLUTANT				
	(usually more than 450 L in capacity) Not possible				
	Section 15. Regulatory information				
Safety/health Ca	anadian regulations specifics Refer to Section 2 for the appropriate classification. This product has been classified in				
	accordance with the hazard criteria of the Hazardous Products Regulations (HPR) and of the				
	United States OSHA (29 CFR).				
Environmental	Canadian regulations specifics Refer to Section 3 for ingredient(s) of the DSL				
	vironmental outside regulations specifics				
United States OS	HA information: This product is regulated according to OSHA (29 CFR).				
United States EP	A (Environmental Protection Agency) information: 40 CFR Refer to the ingredients listed in Section 3 & Sections 12; 13 & 14.				
	SA information: Refer to the ingredients listed in Section 3.				
	stection Association (NFPA):				
HEALTH: 1	FLAMMABILITY: 4 INSTABILITY: 1 SPECIAL HAZARDS: Refer to Section 2 & 3.				
	E: 0 = Minimal $1 = Slight$ $2 = Moderate$ $3 = Serious$ $4 = Severe$				
	ition 65: No ingredient known to the State of California to cause cancer or other reproductive harm.				
1	Section 16. Other information				
Date of the lates	t revision of the safety data sheet DATE: 2025-02-06				
References	Safety Data Sheets from manufacturer/supplier & from Canadian Centre for Occupational Health and Safety, CCOHS.				
Abbreviations					
ACGIH	American Conference of Governmental Industrial Hygienists				
ATE	Acute toxicity estimate				
CAS	Chemical Abstract Service				
DSL	Domestic Substance List				
IARC	International Agency for Research on Cancer				
IATA	International Air Transport Association				
IMDG	International Maritime Dangerous Goods Code				
LC	Lethal concentration				
LD	Lethal Dosage				
NIOSH	National Institute for Occupational Safety and Health				
NTP	National Toxicology Program (U.S.A.)				
OSHA	Occupational Safety and Health Administration (U.S.A.)				
PEL	Permissible Exposure Limit				
STEL	Short-term Exposure Limit				
TDG	Transport of dangerous goods in Canada				
TLV	Threshold Limit Value				
TSCA	Toxic Substances Control Act				
TWA	Time Weighted Average				
WHMIS	Workplace Hazardous Materials Information System				
liability whatsoeve	knowledge, the information contained herein is accurate. However, neither the above named supplier nor any of its subsidiaries assumes an r for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibilit terials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that azards that exist.				